

Mounting the Camera



Mount the camera to the camera mounting bracket using the 1/4" BSW camera screw, slide the camera forward and ensure that the lens is inside the hood. Use the hood slide screw to centre the lens inside the hood and place the black light excluder around the lens. Secure it using the drawstring.

Camera Balancing



Loosen the two screws (marked A in the picture) so that the hot shoe plate will slide back and forth.

Mount the unit with camera attached to the tripod and slide the unit back and forth until you achieve a balance.

Then retighten the screws.



Straight-read Assembly



1. Place your SSP07 on a smooth, level surface. Remove the thumbscrews holding the hood and monitor mounting plate.

2. Remove the two thumbscrews attaching the monitor mounting bracket to the drop bracket.



3. Remove the thumbscrews securing the monitor to the monitor mounting bracket.

4. Align the bolt on the back of the monitor mounting plate with the hole in the centre of the drop bracket.



5. Secure it to the drop plate with the knob.

6. Attach an optional pistol grip to the hot shoe plate on the underside of the SSP07 unit.



7. Now attach your camera to the camera mounting bracket using the screw supplied.



Camera screw

SSP07 Prompter Guide



Components

A	Hood and glass
B	Monitor
C	Hood Bracket
D	Camera Bracket
E	Hot Shoe Plate
F	Drop Bracket
G	Monitor mounting plate
H	Hood thumbscrew
I	Hood Slide Screw



Assembly

1. Remove the unit from its case and carefully place the glass side face down, onto a level surface.



2. Loosen the thumbscrews holding the monitor mounting plate and raise the monitor.

3. Align the metal tongue of the monitor mounting plate with the slot in the drop bracket and carefully insert the tongue into the slot. (fig. i)

4. Tighten the thumbscrews to secure the monitor mounting plate. (fig. ii)



fig. i

fig. ii

5. Attach the tripod camera mounting plate to the hot shoe plate on the underside of the SSP07 unit.




6. Slide the on-camera unit onto your tripod.



7. Loosen the two thumbscrews holding the monitor mounting plate and hood assembly.

8. Raise the hood assembly to the vertical position and tighten the thumbscrews.



Vertical position

9. Rotate the camera bracket so that it is on the top of the unit and behind the hood.



10. Fix your camera to the bracket using the camera screw. Slot the bracket over the thumbscrews and tighten all four thumbscrews to secure it.



11. Attach the large plug to the socket on the side of the monitor.

12. You can use either a composite or VGA video input by connecting the appropriate cable.

